Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080154-3

RECEIVING INSPECTION REPORT

[illegible] MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. [illegible]3

RECEIVED FROM PLANT #5

DATE REC'D 3-21-57

P.O. NO.

VENDOR PACKING SLIP NO.

	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO
CHARGE TO	322		6	C	20					

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
3	733296 Lid & Spring Assly Switch IPS #04799	3	✓	

RECEIVED BY J. Barcelos 1062

INSPECTED BY HC

DATE 3-21-57

REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11644

RECEIVED FROM Allied Control

DATE REC'D 3-21-57

P.O. NO. 65528

VENDOR PACKING SLIP NO.

	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
CHARGE TO	322	600000	102	0	2	1				

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
14	730125-18 Relay Sub Min. 2 PDT, Allied MHB-6D-26.5	14	✓	

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080154-3

RECEIVED BY

INSPECTED

2-23-57

REJECTS RETURNED